

VALUE OF "0" INDICATES THAT I.R. IS NOT TRANSMITTED FOR THAT 0.7

ms TIME PERIOD.

RECEIVER IC IS SHARP GP1U901X.


CARRIER FREQUENCY IS 38KHZ.

THE BREAK AND REPEAT OCCUR IF KEY IS HELD DOWN.


TIMING IS SIMILAR TO SHARP TV CODE 00121.


MESSAGE LENGTH = 17.66 ms. START BIT DO, 8 BITS OF DATA














F/G.//






FIG. 16






FIG. 17






FIG. 18